

RPL1000 MONITOR REPAIR PARTS

LIST PRICES

Effective: July 1, 2026
Revised: June 15, 2026

Ord. No.	List Price
1.5WP75	76.97
10-174ALFFRO	129.60
10WP75	124.06
1WP75	81.88
2.5WP75	85.83
2WP75	84.51
3WP75	87.05
4WP75	89.66
5WP75	92.18
6WP75	94.81
7WP75	97.43
8WP75	99.98
AB10	30.82
AB5	15.39
AB5.5	14.83
AB6	14.83
AB7	14.83
AB8	14.38
AG10	253.42
AG4	39.85
AG5	40.73
AG5.5	38.41
AG6	41.48
AG7	68.98
AG8	73.60
APC14	56.92
APC24	189.23
APC34	69.07
APC45	112.70
APC46	149.28
APC55	264.27
APC56	288.88
APC7	5.60
APC7S	8.15
BF24	53.03
BX220	4.14
C00FRO	15.68
C125FW	285.00
C125W	309.79
C20FW	345.28
C2FW	197.75
C210	59.59
C260FRO	86.76
C311	86.76
C5125BW	335.58
C5BW	258.87
C6125BW	349.80
C6BW	321.68
C6W	195.97
CA82F	78.57
CA82M	72.61

Ord. No.	List Price
CD90	38.43
C80FFRO	80.98
C80M	57.59
CA387M	135.47
CF90	39.45
CJ90	55.74
CXF1	68.42
DP11	15.44
DP12	16.69
DP134	106.23
DP16	119.17
DP17	4.55
DP18	99.57
DP195	37.99
DP196	49.50
DP197	43.42
DP20	4.40
DP202P	328.68
DP22	3.17
DP25	47.07
DP26	26.62
DP27	206.31
DP30	221.42
DP31LF	29.24
DP35	235.29
DP39	185.72
DP40	120.93
DP46	15.49
DP47	75.24
DP48	15.69
DP49	4.51
DP50	339.09
DP52	389.38
DP53FRO	298.39
DP56	344.56
DP57	148.34
DP58	1801.42
DP59	269.01
DP60P	184.86
DP61	99.77
DP62	19.00
DP66P	314.90
DP68P	333.86
DP70	8.56
DP72	424.02
DP76	51.44
DP90	103.10
DRPT1	92.83
DRPT1.5	96.59

Ord. No.	List Price
DRPT10	148.64
DRPT2	109.09
DRPT2.5	102.41
DRPT3	115.44
DRPT4	130.91
DRPT6	124.22
DRPT7	130.04
DRPT8	159.68
E42S	0.36
E49N	2.78
E80	4.55
EP54	23.59
FM7S	2.90
G150	62.85
G18.4X3	205.16
G18.6X4	332.95
GI11T	5.81
GO21	6.81
H211A	14.41
H215DFRO	28.56
H220DAXFRO	21.79
H222WMFRO	158.40
H228	6.61
H230AFRO	47.93
HA152	232.04
HA153	373.11
HA155	70.74
HA20	63.71
HA52	30.49
HA5FRO	218.21
HC50	1057.57
HC50A	2288.03
HD140	1047.78
HD140A	1316.33
HD156FRO	273.81
HD160	509.80
HD189	87.46
HD190	59.07
HD34	9.61
HD5	235.48
HD54	60.11
HD59	6.92
HD64	50.72
HD67	25.05
HD69	55.31
HD70	4.40
HD71	21.68
HD71G	17.52
HD90	74.94
HF153	271.28

Ord. No.	List Price
HF30	8.83
HF33	8.56
HF50	814.49
HF57	5.88
HF61A	30.06
HK320	5.02
KP145S	48.66
L148	96.85
L168	103.49
LK4S	77.56
MP36	68.47
NA115	9.11
NA17	128.62
NA233	445.12
NA234	497.42
NA31	100.69
NA31P	131.50
NA333	460.48
NA39	11.59
NA40	272.90
NA80	182.35
NB15	23.73
NC15	19.09
NC16	4.48
NC47	35.58
NC65	52.53
O200	252.10
O31LF	47.44
O37FRO	429.02
O38FRO	158.61
O400	113.97
O41	4.40
O42	12.76
O43	39.45
O460	39.66
O50	162.15
O52	242.07
O53	15.44
O54	16.92
O6	130.45
O7	718.69
O80	30.49
O81	11.70
O9	118.13
ORH10	4.56
PA138TLF	55.04
PA140TLF	108.90
PA140TPLF	105.40
PA141TLFFRO	156.20
PA142TLFFRO	218.64

RPL1000 MONITOR REPAIR PARTS

LIST PRICES
Effective: July 1, 2026

Ord. No.	List Price
PA143TLFFRO	191.95
PA144TLF	38.51
PA144T	21.78
PA154	40.82
PA155MLF	308.86
PA155MT	315.18
PA159	59.47
PA709	8.04
PC127	3.88
PC286	4.11
PC286S	4.51
PC287	7.90
PC288	4.77
PC330	47.78
PC332	5.50
PC335	82.15
PC335A	174.81
PC371	6.49
PC386	4.55
PC415	4.55
PC417	4.69
PC42	562.82
PC429	34.81
PC433	4.24
PC433S	7.79
PC434S	2.51
PC45	11.88
PC95	10.63
PH1FRO	80.44
PH2FRO	126.96
PH50	34.94
PH88	10.81
PH8N	4.06
PJ50	3.18
PJ50S	8.79
PK13	4.69
PK29	26.72
PK97	3.54
PL105	210.52
PL10S	15.52
PL150B	15.38
PL151B	19.78
PL2	17.64
PL21	31.51
PL214	62.41
PL215A	67.92
PL216A	70.57
PL21S	7.57

Ord. No.	List Price
PL221	68.46
PL225	69.61
PL24	162.50
PL3	13.06
PL304	81.31
PL304.2	85.50
PL304.2BLF	168.47
PL304BLF	161.35
PL305	75.11
PL305BLF	162.64
PL305.2	89.28
PL305.2BLF	174.23
PL305.62	44.09
PL306	82.83
PL306.2	79.82
PL306.2BLF	171.73
PL306BLF	167.39
PL34	35.94
PL40	9.28
PL49	186.47
PL4S	8.80
PL50	19.79
PL83	70.17
PL84	61.48
PL8401	237.34
PL84012	281.62
PL84012BLF	336.68
PL8401BLF	329.95
PL8431	248.33
PL84312	287.84
PL85	65.33
PL8501	245.67
PL85012	287.27
PL85012BLF	366.43
PL8501BLF	305.86
PL8521	247.19
PL86	52.36
PL8601	256.27
PL86012	295.78
PL86012BLF	308.30
PL8601BLF	342.76
PL8621	250.60
PL86212	292.01
PL87	35.13
PL98	205.19
PN13	9.18
PR1ALF	75.76
PR3	4.49

Ord. No.	List Price
PS101	2.95
PS110	14.24
PS111	6.43
PS111S	9.27
PS116	42.69
PS120	27.38
PS123	8.86
PS132	3.57
PS132S	4.36
PS134	95.56
PS135	104.47
PS136	111.31
PS139D	13.74
PS151	184.79
PS156	240.22
PS164	41.96
PS165	45.69
PS166	71.13
PS166.6	67.21
PS167	74.41
PS168	149.81
PS170	173.15
PS171	3.76
PS178	163.45
PS181	6.07
PS182	19.82
PS184	68.84
PS185	78.65
PS186	89.11
PS186.6	109.68
PS187	110.74
PS188	195.59
PS189	193.69
PS194	11.22
PS195	13.79
PS196	15.96
PS196.6	15.54
PS197	20.44
PS198	34.44
PS199	4.33
PS2	3.68
PS216	107.01
PS217	163.80
PS218	440.17
PS219	7.05
PS220	7.63
PS221	4.37
PS221S	18.52

Ord. No.	List Price
PS262	13.18
PS263	17.51
PS265	19.11
PS27	3.47
PS282LF	115.18
PS29	4.45
PS341	330.07
PS342	29.38
PS350	563.94
PS365S	135.95
PS374	86.20
PS375	94.29
PS376	112.02
PS376.6	117.27
PS377	112.61
PS421	11.24
PS422	297.59
PS423	11.02
PS425	15.03
PS427	29.01
PS429	32.01
PS430	38.36
PS44LF	129.83
PS46	7.17
PS464FRO	24.73
PS465FRO	31.65
PS466FRO	62.22
PS535	0.61
PS544	48.65
PS5441	51.32
PS5441P	40.10
PS5451	52.08
PS5451P	54.13
PS5461	55.75
PS5461P	55.75
PS5471	78.68
PS550S	2.63
PS564	7.85
PS565	10.11
PS566A	10.11
PS567	15.74
PS574A	13.13
PS575A	13.31
PS576A	13.31
PS577A	15.19
PS585	4.71
PS585A	10.31
PS585B	5.78

RPL1000 MONITOR REPAIR PARTS

LIST PRICES

Effective: July 1, 2026

Ord. No.	List Price
PS262	13.18
PS263	17.51
PS265	19.11
PS27	3.47
PS282LF	115.18
PS29	4.45
PS341	330.07
PS342	29.38
PS350	563.94
PS365S	135.95
PS374	86.20
PS375	94.29
PS376	112.02
PS376.6	117.27
PS377	112.61
PS421	11.24
PS422	297.59
PS423	11.02
PS425	15.03
PS427	29.01
PS429	32.01
PS430	38.36
PS44LF	129.83
PS46	7.17
PS464FRO	24.73
PS465FRO	31.65
PS466FRO	62.22
PS535	0.61
PS544	48.65
PS5441	51.32
PS5441P	40.10
PS5451	52.08
PS5451P	54.13
PS5461	55.75
PS5461P	55.75
PS5471	78.68
PS550S	2.63
PS564	7.85
PS565	10.11
PS566A	10.11
PS567	15.74
PS574A	13.13
PS575A	13.31
PS576A	13.31
PS577A	15.19
PS585	4.71
PS585A	10.31
PS585B	5.78

Ord. No.	List Price
UC285	145.80
UC288	98.03
UC289	136.38
UC291	1269.14
UC294	916.57
UC334	1535.85
UC391	1805.52
UC491FRO	1682.64
UC66	3.14
UC670	1150.46
UE105	155.97
UE196	99.94
UE197	59.16
UE234	910.50
UE34	800.88
UE383D	1039.75
UE44	778.58
UE560	917.95
UE560D	1507.74
UE560M	1283.42
UE96	114.70
UG15	57.29
UG191	7.53
UG260	208.76
UG333A	423.36
UG335	209.19
UG54	3589.33
UG54	17.84
UG54G	25.87
UG7BH	326.47
UG7SPECIAL	295.86
UH15	44.08
UH85	114.34
UJ140	5105.14
UJ144	1085.19
UJ145	244.67
UJ15	65.78
UJ154	19.10
UJ155	11.78
UJ174	691.79
UJ175	414.64
UJ176	460.30
UJ177	13.20
UJ177S	26.58
UJ178	7.31
UJ32	741.19
UJ3222	3233.56
UJ50	137.68

Ord. No.	List Price
UJ7	206.62
UJ8	83.06
UJ80	29.07
UJ85	423.22
UJ90	76.42
UK15	69.29
UK188	9.48
UK251	9.77
UK254X29	209.72
UK308	87.40
UK606	5175.90
UK671	406.11
UK673	671.84
UK674	726.88
UK693	1090.16
UK7	264.12
UK72	234.36
UK7M	204.27
UK850	1135.02
UK94	253.24
UL102	483.47
UL15	134.21
UL168	393.23
UL254	670.01
UL97	1006.15
UL97P	1006.15
UM140	11.06
UM15	158.84
UM60E	7784.73
UM7	233.77
UM72	273.71
UM850	2080.19
UN120	11.42
UN122	3.66
UN15	162.14
UN170	74.45
UN243	4.32
UN243W	2.21
UN320A	323.37
UN7	349.10
UN72	297.32
UN73S	21.09
UN81	6.91
UN850	3398.84
UQ15A	263.29
UQ66	944.06
UQ72	384.67
UR15A	306.58

Ord. No.	List Price
UR72	384.67
UR7A	#N/A
UR850A	3054.34
US15A	325.37
US72	545.42
WA13	23.23
WA14C	81.80
WA8	428.17
WA9	170.82
WBAG	52.59
WBAG1	61.75
WBAG3	157.39
WBAG4	168.35
WBAG5	506.74
WBAG6	61.75
WBAG7	71.10
WE1	15.97
WE1P	8.96
YB60	618.85
YB9	790.77
YC218	223.10
YC225	4.21
YC239	50.38
YC240C	391.06
YC241	131.94
YH175	6.02
YH575	6.52
ZA1	56.28
ZA12	267.97
ZA19	38.74
ZA197	33.18
ZA198	12.92
ZA20	235.17
ZA201	207.37
ZA203	676.59
ZA204	38.56
ZA205	18.34
ZA21	11.68
ZA215	41.47
ZA22	55.22
ZA220	9.99
ZA222	11.68
ZA223A	125.45
ZA23	15.72
ZA230	589.91
ZA231	205.40
ZA24	320.70
ZA240	284.85

RPL1000 MONITOR REPAIR PARTS

LIST PRICES
Effective: July 1, 2026

Ord. No.	List Price
ZA246	16.08
ZA26	9.40
ZA28	153.58
ZA333	128.17
ZA406	309.64
ZA506	235.25
ZA512	51.28
ZA513	63.16
ZA514	56.69
ZA516	41.89
ZA517	24.40
ZA524	71.76
ZA526	111.67
ZA527	7.53
ZA532	3.98
ZA6	18.16
ZA602	8.14
ZA61	112.74
ZA63	20.41
ZA64	2.68
ZA70	5.24
ZA8	1005.18
ZA80	3.74
ZA94	62.32